

P
Tech
M

THE MIAMI CONSERVATIONIST

Volumes I and II—August, 1918 to July, 1920

G. L. Teeple, Assistant Engineer, Editor



Press of
The General Printing Co., Dayton, Ohio
1920

STATE OF OHIO

The Miami Conservancy District

Board of Directors

Edward A. Deeds, President	Dayton, Ohio
Henry M. Allen	Troy, Ohio
Gordon S. Rentschler	Hamilton, Ohio
Ezra M. Kuhns, Secretary	

Arthur E. Morgan	Chief Engineer
Chas. H. Paul	Assistant Chief Engineer
C. H. Locher	Construction Manager
Oren Britt Brown	Attorney

THE MIAMI CONSERVANCY BULLETIN—INDEX

Volumes I and II, August, 1918, to July, 1920

Note. The index is alphabetical, and includes both articles and illustrations. Pictures, however, illustrating an article, are only indicated by an asterisk *, following the title of the article. Illustrations which do not accompany an article are designated by the abbreviation "Fig." Roman numerals designate the volume. Arabic numerals designate the page. The abbreviation (e) designates an editorial. With articles of a page or more, the length in solid columns is given.

An Author's Index will be found at the end of the general index.

A

Accounting Division*	II	63
Age, In Business (Chart) (e)	II	100
Aggregate—See Gravel.		
Antioch College, Description of courses (e)	II	180
Mr. Morgan called to be President of (e)	I	67
Appraisal—See under Legal.		
Armistice, Effect of the (e)	I	67
Association.		
Conservancy Athletic, Organization of	I	77
Camp Community, Community feeling of (e)	I	84
Taylorville Community, 2 columns	I	94
Riverside Community	I	126
Six Months' Progress of the Camp Community, 5 columns*	I	172
American Association of Engineers		
Address by Prof. F. H. Newell (e)	II	4
Assessment, Second Annual Conservancy (e)	II	51
Administration, Camp and School, Change in	I	92
Atlas of Selected Contract and Information Drawings, in Technical Reports, Price of (e)	I	148
Auto Service, Notice to Conservancy Employees	I	47

B

Bacteria. Function of, in Sewage Disposal *, 5 columns	II	155
Banks, Spoil—See under Spoil Banks		
Baltimore and Ohio R. R.		
See under Railway Relocation		
Beebe, J. C. See Author's Index		
Benefits and Damages—See Legal		
Big Four—See Big Four under Railway Relocation.		
Blasting*	I	26
Rock at Conservancy Dams*, 9 columns	II	89
Board of Directors		
Report of, Review of Activities (e)	I	83
Annual Report of (e)	II	67
Bock, C. A.—See Author's Index		
Bolton, John W., Goes to North Carolina	I	111
Bonds—See under Finances		
Borrow Pit		
Beginning the Hydraulic Fill at Taylorville	I	57
For Hydraulic Fill at Taylorville, Fig. 86	I	96
At Englewood (e)	II	100
Bridge		
Big Four and Erie R. R. over Mad River, Fig. 143	I	162
Construction Trestle for the fill at Picayune Creek, B. & O. R. R., Fig. 88	I	98
At Picayune Creek, B. & O. R. R., Fig. 93	I	105
Underpass for Highway and Ohio Electric, Fig. 104	I	114
Concrete Culvert on Relocation B. & O. R. R., Taylorville, Fig. 108	I	123
B. & O.—See B. & O. under Railway Relocation		
Buckeye Street Sewer*, Building of at Hamilton, 3 Columns	II	69
Buildings, Wrecked, at Hamilton, Figs. 94, 95 and 97	I	107
Bulletin		
Foreword (e)	I	3
Scope of (e)	I	3

Bunkhouses—See Cottages under Camps		
Bureau of Public Roads Co-operates with Conservancy Officials	II	140
Bureau of Soils, Washington, D. C., Co-operates with Conservancy Officials	II	140
Business, Age in	II	100

C

Calaveras Dam, Core Material at	II	139
Camps (at the Conservancy Dams)		
Amusements in	I	174
Associations, Community, feeling of (e)	I	84
Administration, Change in	I	92
Cottages*	I	12
Construction, Departure of A. D. Huff	I	119
Conservancy Camps, Effect of Dry Wave on (e)	II	20
Communities Self-Governing Again (e)	I	116
Housing—See Housing		
Influenza and the Conservancy Medical Service (e)	II	68
Organization, Englewood vs. Taylorville	I	126
Progress, Six Months, of Camp Community Associations*	I	172
Rupe's Iceless Refrigerator, Fig. 15	I	14
Sewerage Systems at the*, 5 columns	II	155
Schools—See Schools		
School at Germantown, Fig. 38	II	45
Schoolhouse at Englewood, Fig. 167	II	192
View of completed at Lockington, Fig. 77	I	82
Cars—See Locomotives and Cars		
Celebration, The Liberty Day*	I	77
Cement		
Measurement of, for Concrete	I	142
Mortars in Conservancy Concrete	I	88
Proportions in Concrete	II	22
Proportions at Taylorville *, 6 columns	II	125
Proportions at Lockington	II	9
Tests at Germantown	I	182
Cement Sacks		
Money saved by selling	I	61
Dust Eliminator for Cleaning Empty*	I	143
Chambers, C. C.—See Author's Index		
Channels		
Calculation of Flow in Open, Technical Reports	I	143
Channel Improvement the essential work of the Conservancy at Dayton and Hamilton	I	20
Diversion at Huffman, Fig. 47	I	45
Experiments with Contracted (e)	II	99
Standard Channels	I	20
Standard, Cross section of, etc.*	I	151
Water—See Water Channel		
Chart, Maximum Demand for Electrical Power at Taylorville, Fig. 139	I	158
Cincinnati Formation		
Absence of, at Lockington	II	89
Found in Miami Valley	II	85
Cincinnati Shale	I	120
Excavation for the Conduits in the Germantown Dam	I	181
Circular—See Farm Circular		
Citizens' Relief Committee at Dayton (e)	II	180
Clearing	I	6
Coal		
Saving of, by electrical transmission	I	166
Coal and Copper, cost of (e)	II	68
Collective Bargaining, Labor Policy of the District	I	8
Concrete		
Analysis of, at Englewood	II	22
Block Plant*, 4 columns	II	4, 13
Block Revetment Started at Dayton	II	51
Blocks, cost of, for Miami River Revetment	II	16
Blocks, Making of, for Miami River Revetment	II	13
Breaking Hamilton Pavement, Fig. 57	II	69

MIAMI CONSERVANCY BULLETIN—INDEX

Concrete equipment—See under equipment		
Finishing Surfaces of, at Englewood.....	II	22
Forms at Englewood and Germantown*, 4 columns.....	II	42
Junction with Rock at Englewood, Fig. 135.....	I	155
Mixer at Englewood, Fig. 123.....	I	142
Mixture for Robert Blvd. Wall*.....	II	128
Outlet Structures—See under outlet structures		
Proportioning at Taylorsville*, 7 columns.....	II	123
Proportioning of Conservancy*, 6 columns.....	I	85
Proportions for, at Englewood.....	II	23
Proportions for, at Germantown.....	I	182
Revetment at Dayton, Practical Test of*, 3 columns.....	II	170
Sand and Gravel for, at Englewood.....	II	22
Strength of Conservancy*.....	I	88
Tailrace Construction at Hamilton*, 6 columns.....	II	181
Winter Work at Robert Blvd. Wall*.....	II	128
Concreting		
Affected by Flood of March*.....	I	135
At Taylorsville, Fig. 151.....	II	177
Begins at Huffman.....	I	131
In Winter.....	I	99
In Winter.....	I	105
Layout at Taylorsville*.....	II	143
Plant for Robert Blvd. Wall*, 4 columns.....	II	126
Records broken at Taylorsville.....	II	192
Tower at Englewood, Fig. 145.....	I	162
Work in Winter.....	I	115
Conferences		
Men Responsible for Distribution of Supplies and Materials hold Conference, Fig. 52.....	II	63
Conservancy Law—See Legal.		
Conservancy Project, General View of*, 6 cols.....	I	186
Construction—See also under Blasting, Drilling, Concreting, etc.		
Clearing, Stripping and Cut-off Trenching*.....	I	6
Copper and Coal, Cost of (e).....	II	68
Core Materials, Relative Amounts of in Hydraulic Fill Dams.....	II	138
Cost of		
Coal and Copper.....	II	69
Concrete Blocks (Contract Prices).....	II	16
Cottages.....	I	12
Conservancy Project.....	II	84
Depositing hill-side material in the dam at Germantown.....	II	36
Entire Project up to July 31, 1919.....	II	84
Grading on Baltimore and Ohio.....	II	40
Railway Grading with Stiffleg Derrick Draglines*, 3 columns.....	II	75
Railway Relocation on Baltimore and Ohio R. R.	II	40
Rent, Board, etc., at Camps.....	I	12
Stiffleg Derrick Dragline.....	II	75
Well Drill.....	II	91
Wrecking Property at Hamilton.....	II	12
Cross Dam, built by Plastic Fill at Taylorsville*, 3 columns.....	II	101
Cut-off Trenching at Taylorsville*.....	I	6
Cottages—See under Camps.		
D		
Dams		
At Englewood, Building first section of, Fig. 55.....	II	66
Cross—See Cross Dam.		
Calaveras—See Calaveras Dam.		
Earth Pressures in Conservancy.....	II	45
Hydraulic Fill, Porosity of Gravel Shoulders*.....	II	190
Island Park—See Island Park Dam.		
Measuring Upward Pressure under *, 5 cols.....	II	187
Pressure due to gas under.....	II	187
Relation of, to entire project*.....	I	186
Stability of the Conservancy*.....	II	190
Value of upstream mud blanket.....	II	187
Daubenspeck, H. R. Asst. Engineer at Taylorsville.....	II	123
Day's Work, Length of.....	I	8
Day, Eight-Hour.....	I	8
Dayton—See also under Miami River Improvement.		
Dayton, Progress on the Work at.....		
I, 46, 60, 75, 92, 109, 122, 139, 154, 170, 185.		
II 10, 25, 41, 58, 74, 103, 122, 137, 154, 169, 186.		
Standard Levees and Channels, Spoil Banks, Wrecked Buildings, etc.*, 4 cols.....	I	20
Deaths.		
Mounts, W. R. (e).....	I	100
Williams, C. C. (e).....	I	100
Kirby, James J. (e).....	I	116
Jaycox, T. W. (e).....	II	35
O'Brien, Wm. A. (e).....	I	51
Deeds, E. A.	I	36
Derrick, Transformed for Railway Grading*, 3 columns.....	II	75
Diagram, Progress of Conservancy Work (e).....	II	82
Directors, Reports of Board of (e).....	I 83, II	67
Dragline Excavators.		
Compared with Steam Shovel*, 3 columns.....	I	39
Crossing Stillwater River, Fig. 149.....	II	176
Getting together the Equipment*, 6 columns.....	I	36
Grading with Stiffleg Derrick*, 3 columns.....	II	75
Used in Rock Excavation of the Conservancy Dams.....	II	89
Wrecked in Dayton.....	II 151,	153
Wrecked in Dayton, at work*.....	II	174
Wrecked, How Salvaged*.....	II	174
At Lockington Draglines.....	I	52
Dredge Pipes.		
In Hydraulic Fill*.....	II	108
Friction in.....	II	119
Dredge Pumps.		
At Englewood.....	II	119
Improved Layout at Englewood*, 6 columns.....	II	165
Record of performance at Englewood (e).....	II	148
White Iron Centrifugal Pump Shell.....	II	173
Drift, Glacial, as Material in Conservancy Dams.....	II	85
Drilling in Rock at the Conservancy Dams.....	I 26, II 89,	94
Drills, Use of, at Conservancy Dams for Rock Excavation.....	II	89
Dust Eliminator for Cleaning Empty Cement Sacks, Fig. 125.....	I	143
Dynamite—See Blasting.		
E		
Earth Excavation, Borrow Pit at Englewood Dam, Fig. 83.....	II	97
See also under Excavation.		
Earth Pressures.		
In Conservancy Dams.....	II	45
In Conservancy Dam Cores*.....	II	138
Diagrams of, at Germantown Dam, Fig. 119.....	II	141
Efficiency.		
Of Electrical Transmission compared with steam.....	I	166
Of Steam Construction Plant compared with Electrical Transmission.....	I	166
Of Electrical Transmission Line.....	I	166
Of Turbine Steam Plant.....	I	166
Electrical Equipment—See under Equipment.		
Elephants in The Miami Valley, Fig. 39.....	II	46
Embankment.		
Building Railway by Stiff-leg Derrick*, 3 cols.....	II	75
Hydraulic Fill—See Embankment under Hydraulic Fill.		
Levee—See Levee.		
Plastic Fill at Taylorsville*, 3 columns.....	II	101
Employes (See also Labor, Workman's Compensation Law, etc.)		
Rent of cottages, Board at Mess Halls, etc.....	I	12
Some Figures on.....	I	11
District Medical Service and Influenza*.....	I	55
Employment.		
Qualifications, Methods, etc., in Building up an Engineering Organization, 4 columns (e).....	I	4
Length of Working Day, union labor, etc.....	I	8
Engineer.		
Australian Engineers (e).....	II	52
Chinese Engineers.....	II	46
Visit of Representative Engineers.....	I	179
The American Association of Engineers, Address by Prof. F. H. Newell (e).....	II	4
Qualifications of, for Conservancy Work (e).....	I	4
Englewood.		
Outlet Structure at*, 5 columns.....	II	21

MIAMI CONSERVANCY BULLETIN—INDEX

MIAMI CONSERVANCY BULLETIN—INDEX

Forest Lands.			
The Conservancy Timber and its Management*.	I	101	
5 columns			
Foreword to first number of Bulletin (e)	I	3	
Front Street Sewer at Hamilton	II	72	
Foundations.			
Seepage under when of Porous Material*, 4			
columns	II	187	
Franklin, Progress on the Work at			
II 58, 75, 88, 104, 122, 138, 155, 170, 186			
G			
Gardens.			
Victory (e)	I	131	
At Camps*	I	12	
Geology.			
Of Miami Valley as Affecting Conservancy			
Work	II	85	
Rock Formations at Conservancy Dams*	II	89	
Rock Formation at Huffman Cut	I	26	
Germantown.			
Beginning the Concrete Structure at*	I	62	
Concrete Conduits at*, 4 columns	I	181	
Progress on the Work at			
I 43, 58, 71, 91, 108, 120, 138, 154, 169, 184			
II 9, 24, 40, 57, 73, 86, 102, 121, 137, 154, 168, 185			
The Work at, Fig. 68	I	72, 73	
Giant—See Monitor.			
Goldbeck, A. T.	II	139	
Investigations on Pressure Cells an Aid in Con-			
servancy Work*, 6 columns	II	139	
Government—See Self-Government.			
Grant, Major K. C., Joins Dayton Engineering			
Firm	I	143	
Gravel.			
Aggregates.			
Analysis of at Taylorsville*, 6 columns	II	123	
Voids in at Taylorsville	II	123	
Pea, at Taylorsville	II	126	
Gravel Washer.			
Improvements in at Taylorsville	II	126	
Improvements at Lockington	I	110	
Gravel Washing Plants.			
At Dayton	II	59	
The Conservancy*	I	140	
At Taylorsville*, 6 columns	II	123	
Grizzlies at Englewood	II	118	
Grouting under Bridge Foundation at Hamilton			
Tailrace*, 5 columns	II	181	
H			
Hamilton.			
Elephant Tooth found at	II	46	
Improvement of Channel at*	I	20	
Population of	I	117	
Progress on the Work at			
I 45, 60, 75, 92, 109, 122, 139, 170, 185			
II 10, 25, 41, 58, 74, 87, 103, 122, 137, 155, 169, 186			
Standard Levees and Channels, Spoil Banks,			
Wrecked Buildings, etc.	I	20	
Storm Sewers at, Building*, 4 columns	II	69	
Tailrace at*, 5 columns	II	181	
The Construction Program at*	II	26	
The Problem of the River Channel through*,			
4 columns	II	11	
Hog Box.			
At Englewood	II	118	
At Englewood, Fig. 101	II	114	
Holidays.			
The Labor Day Picnic	I	47	
Labor Policy of the District regarding	I	8	
The Liberty Day Celebration*	I	77	
Honor Roll of Conservancy Men in Army Service,			
2 pages	I	23	
Hospital—See First Aid Hospital.			
Houk, Ivan E.—See Author's Index.			
Calculation of Flow in Open Channels, Tech-			
nical Report	I	143	
Housing.			
The Camps*, Cottages, Mess Halls, Bunkhouses,			
etc., 3 columns	I	12	
Huffman.			
Dam, View of, Fig. 76	I	81	
Excavation—See Rock Excavation.			
Excavation for Outlet, Conduit and Spillway			
Structure Walls, Fig. 155	I	176	
Excavation for Outlet Works below Conduits			
at, Fig. 149	I	168, 169	
Outlet Works at*, 3 columns	II	60	
Progress on the Work at			
I 44, 59, 60, 76, 91, 108, 122, 139, 154, 170, 185			
II 10, 24, 41, 57, 74, 86, 103, 122, 137, 154, 169, 185.			
Railroad, Cut at, Fig. 67	I	71	
Rock Formations at	I	26	
Under Pass at	I	26	
Hydraulic Canal at Hamilton, Fig. 96	I	107	
Hydraulic Development, Interesting, at German-			
town (e)	II	35	
Hydraulic Equipment—See under Equipment.			
Hydraulic Fill.			
At Germantown Dam*	II	72	
At Taylorsville	I	57	
Embankment, Deposition of Material in	I	105	
Excavation on Germantown Hillside (e)	II	35	
Exposition of, Beaches, Levees, Core Pool, Core			
width, etc., 7 columns	II	105	
Excavation—See Hydraulic under Excavation.			
At Englewood and Stream Control*, 7 cols	II	117	
Time Schedule at Englewood, Preparing for			
1920, Fig. 1	II	121	
Winter Work on (e)	II	100	
Work resumed on (e)	II	131	
Hydraulic Fill Pool.			
At Lockington, Fig. 81	II	96	
At Taylorsville, Fig. 84	I	96	
Hydraulic Jump.			
Description of (e)	II	147	
Operates at Germantown and Lockington*			
(e)	II	148	
Hydraulic Jump Pools.			
Use of, for Swimming	II	136	
See Outlet under Outlet Structure.			
Hydrology. A new book by Prof. Mead (e)	II	67	
Imhoff Tanks, Modified form at Conservancy			
Camps*	II	156	
I			
Indicators, Recording. Effect on work and			
morale (e)	II	132	
Influenza.			
District Medical Service and the, Figs. 55, 56	I	55	
Influenza and the Conservancy Medical Ser-			
vice (e)	II	68	
Inspection Trip of the Dayton Citizens Relief			
Commission (e)	II	180	
Island Park Dam, Measuring upward pressure un-			
der*, 4 columns	II	187	
J			
Jaycox, T. W., Death of (e)	II	35	
Johnson, Ray, goes to Dayton Power & Light			
pany (e)	II	4	
K			
Kimball, J. H., in charge of Miami River Improve-			
ment Work	I	153	
Kirby, Death of James J. (e)	I	116	
L			
Labor.			
At Concrete Block Plant	II	15	
Control, The Miami Conservancy District and			
(e)	I	19	
Effect of Dry Wave on Conservancy (e)	II	20	
Effect of Recording Indicators, on (e)	II	132	
Effect of the Armistice on (e)	I	67	
Notice to Conservancy Employees	I	47	
Policy of District	I	8	
Picnic, The Labor Day	I	47	
Required by Draglines*	II	76	
Some Figures on Men and Equipment	I	11	
To the Men of the Conservancy District (e)	I	51	
The Conservancy Shop*	I	68	
War and (e)	I	115	

MIAMI CONSERVANCY BULLETIN—INDEX

Lands.		At Hamilton*—See also under Hamilton.	
Value of Overflowed, on France, Germany and America.....II	54	At Hamilton*.....I	20
Farm, The Conservancy and the Retarding Basins, 4 columns.....I	117	At Hamilton*, 4 columns.....II	26
Farm, Effects of Floods upon.....I	117	Beginning Levee, Fig. 74.....I	80
See also Farm.		Levee, Fig. 63.....I	66
Lane, E. W.		Levee, Finishing the, Fig. 109.....I	125
See Author's Index.		Problem of, at*, 3 columns.....II	11
Experiments with Contracted Channels (e).....II	99	Tailrace, Construction, etc., Fordson Tractor Plant*, 5 columns.....II	80, 87, 181
Lakes at Conservancy Parks.....II	133	Wrecked Buildings at.....II	12
Larsen, Albert, Division Engineer on Railway Relocation. See also under Author's Index.....II	40	At Miamisburg—See under Miamisburg.	
Legal		At Middletown—See under Middletown.	
Appeals against appraisals for benefits and damages (e).....I	100	At Troy—See also under Troy.	
Another Legal Victory (e).....II	3	New Cutoff Channel below Troy, Fig. 162.....II	189
Conservancy Act upheld by the U. S. Supreme Court (e).....I	83	Equipment	
Conservancy wins first Appraisal of Benefits Case (e).....I	132	Concreting Plant for Robert Blvd. Wall*, 3 columns.....II	126
Conservancy Cases in Butler County Disposed of (e).....II	52	Scows and Draglines, Fig. 19.....I	17
Levee.		Concrete Blocks for, Making of*, 3 columns II	13
Beginning the New Levee at Hamilton, Fig. 74 I	80	Channels, Standard.....I	20
Finishing the Levee at Hamilton, Fig. 109.....I	125	Erosion and Deposit of Sediment as related to, 4 columns.....I	149
New Miami River, Levees, Dayton, Fig. 156.....I	177	Levees, Standard.....I	20
Railway Levees at Huffman.....I	26	Relation to Entire Conservancy Project*, 5 columns.....I	186
Standard Sections at Dayton and Hamilton.....I	20	Miamisburg.	
The New Miami River Levee at Hamilton, Fig. 63.....I	66	Progress on the Work at.....II	58, 74, 87, 103, 122, 137, 155, 169, 186
Lincoln, Abraham, Boyhood of. Mr. Morgan's Article in Atlantic Monthly (e).....II	100	Middletown.	
Liberty Loan—See Drives, under War.		Cutoff Channel at West*.....II	64
Lightning Arrester, Alternating Current, at Englewood, Fig. 153.....I	174	Progress on the Work, at.....II	58, 75, 88, 104, 122, 138, 155, 170, 186
Limestone in the Miami Valley.....II	85	Monitor.	
Locher, Chas. H., Appreciation of (e).....II	68	New Hydraulic for Lockington*.....II	136
Work on Equipment*, 4 columns.....I	36	Monument, For Conservancy Dams* (e).....II	132
Lockington.		Morgan, A. E.	
Progress on the work at.....I	43, 58, 74, 91, 108, 121, 138, 154, 169, 184	Called to be President of Antioch College (e) II	180
II 10, 24, 40, 57, 73, 86, 102, 121, 137, 154, 169, 185		Author of The Miami Valley and the 1913 Flood.....I	142
Gravel Washer, Improvements.....II	126	Article on Abraham Lincoln (e).....II	100
Working Layout*, 4 columns.....I	52	Mortar, Cement, in Conservancy Concrete.....I	88
Outlet Structure*, 3 columns.....II	7	Motive Power—See Transportation under Equipment.	
Locomotives and Cars.		Motors.	
Getting together the Equipment*, 4 columns.....I	36	Drying out of Flooded Electric (e).....II	164
The Work at Lockington*, 4 columns.....I	52	Getting together the Equipment*, 3 columns.....I	36
See also Transportation under Equipment.		Electric, Why Chosen for Conservancy Work* I	125
		Induction Motors.....I	125
		Mounts, Death of W. R. (e).....I	100
		Mud—See River Mud.	
		Mud Run, Concrete Forms for Big Four Bridge at, Fig. 66.....I	70
		N	
		Newell, Prof. F. H. Address to American Association of Engineers (e).....II	4
		New Osborn (e).....II	116
		Night Schools started at the Camps.....I	57
		O	
		O'Brien, Wm. A., Obituary (e).....I	51
		Ohio Electric—See under Railway Relocation.	
		Organization.	
		Building up an Engineering, 3 columns (e).....I	4
		Englewood vs. Taylorsville on Camp Organization.....I	126
		Of the Conservancy Athletic Association.....I	77
		Some Figures on Men and Equipment.....I	11
		Outlet Structures.	
		Concrete for.	
		Arches at Germantown, completed (e).....I	131, 163
		At Englewood, Fig. 51.....I	50
		At Englewood, Fig. 3.....II	2
		At Huffman (e).....I	131
		At Huffman Dam, Fig. 2.....II	2
		At Taylorsville*, Fig. 44.....II	53
		Completion of Concrete Arches at Germantown (e).....I	131
		Concreting at Germantown, Fig. 60.....I	64
		Concrete layout for, at Taylorsville, Fig. 121 II	143
		Concreted Section of Outlet Conduits at Germantown, Fig. 103.....I	114
		Concrete Structure at Germantown, Beginning of.....I	62
		Concrete Work on begins at Huffman (e).....I	131

MIAMI CONSERVANCY BULLETIN—INDEX

Concrete Work at Taylorsville, Fig. 80.....	I	95
Conduits at Englewood, Fig. 79.....	I	85
Conduits at Lockington, Figs. 80 and 81.....	I	87, 88, 89
Conduits, Finished Section at Englewood, Fig. 82	I	90
Conduit, Forms at Englewood and Germantown*, 4 columns.....	II	42
Conduits.		
At Germantown, Figs. 105 and 106.....	I	117, 118
Concreted Section of Outlet Conduits at Germantown, Fig. 103.....	I	117
Conduits and Traveling Truss at Germantown, Fig. 103.....	I	117
Velocity through, etc.....	I	27
Excavation for.		
At Englewood, Fig. 57.....	I	59
At Germantown, Fig. 58.....	I	61
At Huffman, Fig. 87.....	I	97
At Taylorsville, Fig. 68.....	I	72
At Taylorsville, Fig. 41.....	II	48
At Taylorsville, Fig. 151.....	II	177
At Taylorsville, Fig. 112.....	I	128
Below conduits at Huffman, Fig. 149.....	I	168, 169
Cofferdam at Taylorsville, Fig. 73.....	I	80
Conduits and Traveling Truss at Germantown, Fig. 105.....	I	117
Hydraulic Jump Pool at Taylorsville, Fig. 142	I	161
Inlet Channel at Lockington, Fig. 126.....	I	144
Outlet for.		
At Englewood, Construction of, Concreting, etc.*, 4 columns.....	II	21
At Lockington, General Description of Working layout*, 4 columns.....	I	52
At Lockington, Construction of, Concreting, etc.*	II	7
Completion of Three of the Five Structures (e)	I	179
Description of Progress on, at Englewood, Fig. 16	II	18
Excavating Outlet at Englewood, Fig. O.....	I	1
Outlet Channel at Lockington, Fig. 82.....	II	96
Panorama of, at Taylorsville, Fig. 107.....	I	120, 121
Panorama Showing Relation of Huffman, to Railway Relocation, Fig. 40.....	II	47
Problem of, with General Description*, 3 columns	I	27
Work on, at Germantown, Fig. 68.....	I	72, 73
Two Types of*	II	5
Outlet Works—See Outlet Structures.		
P		
Parks.		
At Conservancy Dams*, 5 columns.....	II	132, 133
Open to Public, Notice of.....	II	136
Sewer Extension at McKinley*.....	II	59
Paul, Chas. H.		
Speech at American Association of Engineers (e)	I	4
Getting Together the Equipment*, 5 columns.....	I	36
Picnic, The Labor Day.....	I	47
Pile Driving for Hamilton Tailrace*.....	II	181
Pipe.		
Dredge—See Dredge Pipes.		
Getting Together the Equipment*, 5 columns.....	I	36
Window—See Window Pipe.		
See Hydraulic under Equipment.		
Poetry.		
The Dam, "Anatole Feldman".....	I	11
Pool, Hydraulic Jump, its Function*.....	I	29
Porter-Shirley, C. W., Departure of.....	I	159
Power, Warning against Use of Conservancy Dams for Water, Fig. 113.....	II	132
Progress.		
Dayton River Improvement (e).....	I	132
Englewood.		
Completion of three of the Five Conduit Structures.....	I	179
Germantown, Englewood, Lockington (e).....	I	179
Germantown.		
At Germantown up to March, 1898, Flood Level	II	59
Completion of three of the Five Conduit Structures.....	I	179
Englewood, Lockington (e).....	I	179
Diagram for Lockington, Fig. 8.....	II	8
Taylorsville.		
Records Broken at Taylorsville.....	II	192
Railroads.		
On the Tracklaying (e).....	II	20
Railway Construction nearly finished (e).....	II	131
Annual Report of the Board of Directors (e).....	II	67
At the Dams*	I	6
Effect of Flood on Conservancy Work and Equipment*, 4 columns	II	151
How the Flood of March 15-19, 1919 affected Construction work*, 4 columns.....	I	135
In Winter (e).....	I	115
Map showing Work of the Miami Conservancy District, Fig. 157.....	I	178
Of the Conservancy Schools	I	191
On the Conservancy Project (e)	II	83
Chart, Fig. 71 (e).....	II	82
Table (e)	II	84
Progress of Dam Construction Commended by D. W. Mead (e)	II	4
Progress on the Ouellet Works (e).....	II	52
Progress on the Work, Monthly Reports.....		
I 43, 58, 71, 91, 108, 120, 138, 154, 169, 184 II 9, 24, 40, 57, 73, 86, 102, 121, 137, 154, 168, 185		
Six Months' Progress of the Camp Community Association*, 4 columns.....	I	172
The Report of the Board of Directors (e).....	I	83
The Work of the Conservancy—A Bird's Eye View*, 5 columns.....	I	186
Publications of the Miami Conservancy District		
Technical Reports summarised, etc.....	I	142, 143
Farm Division Circulars "e".....	II	36, 68
Pumps		
See Hydraulic under Equipment		
Getting Together the Equipment*, 5 columns.....	I	36
For Sumps at Lockington.....	I	52
Pressure Cells		
In Conservancy Dams.....	II	45
At Germantown "e".....	II	115
In Conservancy Dam Cores*, 6 columns.....	II	138
Towers*	II	140
R		
Railway Relocation		
Baltimore and Ohio Railway		
Baltimore and Ohio Railway Relocation*, 3 columns	II	37
Bridge at Picayune Creek, Fig. 93.....	I	105
Concrete Culvert, at Taylorsville, Fig. 108.....	I	123
Cost of	II	40
Construction Trestle for the Fill at Picayune Creek, Fig. 88.....	I	98
Stone Arch Bridge at Hamilton*, 5 cols.....	II	181
Tracklaying on, Fig. 15.....	II	17
Work at Hydraulic Fill, Delayed by "e".....	II	131
Big Four and Erie Railways		
Alignment in Huffman Basin*, 3 columns.....	I	26
Concrete Forms for, at Mud Run, Fig. 66.....	I	70
Cut at Huffman, Fig. 69.....	II	80
Cut at Huffman Hill, Fig. 67.....	II	70
Panorama showing Relation of to Huffman Outlet Works, Fig. 40.....	II	47
Relation of, to Huffman Dam (with Profile, Map, etc.*)	II	61
Relation to Springfield Pike (Profile and Map) Fig. 49, 50.....	II	61
Relocation at Huffman Basin*, 3 columns.....	I	25
Underpass for Highway and Ohio Electric, Fig. 104	I	114
Ohio Electric Railway		
Grading with Stiffleg Derrick Draglines*, 3 columns	II	75

MIAMI CONSERVANCY BULLETIN—INDEX

MIAMI CONSERVANCY BULLETIN—INDEX

Technical Reports	
A Word About.....	I 175
"Calculation of Flow in Open Channels" (Part IV) Off the Press.....	I 70
Comment on "e".....	I 84
History of Flood Control Project.....	I 22
List and Description of.....	I 142
New One Out, Part VI "e".....	I 148
Timber	
The Conservancy, and Its Management*, 4 columns.....	I 101
See also Trees	
Timbering for Hamilton Sewer Trenches*.....	II 69
Tippicanoe City, Construction Work at.....	II 64
Tower—See Tower under Concreting and under Pressure Cell.	
Track-Laying	
Contract for Track-laying Let "e".....	II 4
Progress on the Track-laying "e".....	II 20
Transportation Equipment, see Transportation under Equipment.	
Trees	
At Conservancy Parks, Varieties, etc.*.....	II 133
Conservation of, Dayton "e".....	II 20
See also Timber.	
Trench, Timbering for, at Hamilton*.....	II 69
Trestle, see under Bridge.	
Troy	
Progress on the Work at.....	II 74, 88, 169, 186
New Cut-off Channel Below, Fig. 162.....	II 189
Trilobite	
The Huffman Dam, Description, Fig. 166.....	I 190
U	
Underpass at Huffman.....	I 26
W	
War	
And Labor "e".....	I 19, 35, 115
Appeal for Bonds.....	I 160
Armistice, the Effect of the "e".....	I 67
Chest.....	I 7
How the Loan Went Through.....	I 62
Liberty Day Celebration*.....	I 77
Liberty Loan, The Fourth "e".....	I 35
Liberty Loan, Organization of the District for the.....	I 42
Liberty Loan Bonds, Paying for "e".....	I 67
Salvation Army Drive "e".....	I 180
The Red Cross Drive.....	I 78
The Return of the Men From "e".....	I 83
The Victory Liberty Loan "e".....	I 147
To the Men of the Conservancy District, Appreciation "e".....	I 51
Victory Loan Drive "e".....	I 163
Victory Gardens "e".....	I 131
War Service Notes.....	I 30, 46, 63, 78
Water Power, Warning Against Use of Conservancy Dams for* "e".....	II 132
Water	
Pipe Layout at Germantown, Fig. 133.....	II 157
System at Camps.....	I 12
Water Channel, Deep, at Hamilton.....	II 26
Weather	
The Conservancy Weather and Flood Warning Service*.....	I 93
Heavy October Rainfall "e".....	II 52
For Monthly Weather Reports, see "River and Weather Conditions."	
Weather Service	
The Conservancy Weather and Flood Warning Service, Purpose, Value, Location of Stations, Equipment, Fig. 83.....	I 93
Temperatures, Hot Wave, August 5, 6, 1918.....	I 31
Williams, C. C., Death of "e".....	I 100
Window Pipes	
At Germantown and Taylorsville*.....	II 109
Wire-Bending Machine.....	II 15
Woodward, S. M.....	I 30
Hydraulic Jump and Backwater Curves, Technical Reports.....	I 142
Wood Street Sewer, Hamilton*.....	II 71
Wrecked Buildings, see Wrecked Buildings under Miami River Improvement.	

Authors' Index

Beebe, J. C.	
Hydraulic Jump and Backwater Curves in Technical Report.....	I 142
Blackwell, F. G.	
Assistant Engineer, reports progress on lower river work. See Progress on the Work, under Progress.	
Bock, C. A.	
History of the Miami Flood Control Project.....	I 142
Division Engineer, gives monthly report on Dayton river work. See Progress of the Work, under Progress.	
Calland, J. W.	
The Conservancy Timber and Its Management*, 4 columns.....	I 101
Chambers, C. C., Division Engineer, gives monthly report on Huffman Dam. See Progress on the Work, under Progress.	
Eiffert, C. H., Division Engineer, reports on river improvement at Hamilton. See Progress on the Work, under Progress.	
Floyd, E. N., Division Engineer, reports progress on the Railway Relocation.....	I 46, 61
Floyd, O. N.	
Division Engineer, reports on the Taylorsville Dam. See Progress on the Work, under Progress.	
Foerste, Aug. F.	
The Huffman Dam Trilobite.....	I 190
Elephants in the Miami Valley.....	II 46
Griffin, A. F.	
Assistant Engineer, reports on river improvement at Troy. See Progress on the Work, under Progress.	
Horne, H. W.	
Assistant Division Engineer, reports on Englewood Dam. See Progress on the Work, under Progress.	
Houk, Ivan E.	
District Forecaster, reports on river and weather conditions. See Progress on the Work, under Progress.	
Calculation of Flow in Open Channels, Technical Report.....	I 143
Jones, Barton M.	
Division Engineer, reports on Lockington Dam. See Progress on the Work, under Progress.	
Kent, Arthur H.	
Englewood vs. Taylorsville on Camp Organization.....	I 126
Lane, E. W.	
Assistant Engineer, reports on river improvement at Troy. See Progress on the Work, under Progress.	
Experiments with Contracted Channels.....	II 99
Larsen, Albert	
Division Engineer, reports on railway relocation. See Progress on the Work, under Progress.	
Matthes, G. H.	
New Technical Report Off the Press.....	I 70
A Word About Our Technical Reports.....	I 175
McCurdy, H. S. R.	
Division Engineer, reports on Englewood Dam. See Progress on the Work, under Progress.	
The Outlet Conduits at Englewood*.....	II 21
Stream Control and Hydraulic Fill at Englewood*.....	II 117
Improved Dredge Pump Layout at the Englewood Dam*.....	II 165
McWhorter, R. B.	
Building the Hamilton Storm Sewers*.....	II 69
Paul, Chas. H.	
In Memoriam—Alfred Boardman Mayhew*.....	I 10
Pauls, Arthur L.	
Division Engineer, reports on Germantown Dam. See Progress on the Work, under Progress.	
Smith, S. Graham	
The Conservancy Farm Land Policy.....	I 101
Smith, Walter M.	
The Conduit Forms at Englewood and Germantown*.....	II 42

